

## **Manual control screen changer**

### **Introduction of Manual screen changer**

- ◆ Easy installation and operation.
- ◆ The operation handle can be adjusted according to the workshop position.
- ◆ Unique rigid material, seal-compensation, long service life.
- ◆ The position is precise during screen changing.
- ◆ It is suitable for 90mm extruder or less than 90mm extruder plant.




### **Application of Manual control screen changer**

Nearly all the polymers are fit for screen changer, such as PC, PMMA, PET, PS, PU, PP, PE, EVA, ABS, etc.

- ◆ Non-woven.
- ◆ Granulation.
- ◆ Pipe.
- ◆ Plate.
- ◆ Sheet.
- ◆ Cast film.s

**Structure of Manul screen changer**




**Parameters of Manual screen changer**

Type	Capacity (kg/h)	Dimension (mm)			Screen size		Heater	
		L1	L2	L3	Diameter (mm)	Area (cm <sup>2</sup> )	Voltage (v)	Power (w)
ZB-ACB-50	30-85	150	165	540	50	20	230/400	5200
ZB-ACB-70	75-200	160	170	560	70	38	230/400	5400
ZB-ACB-90	100-290	170	185	580	90	64	230/400	5800
ZB-ACB-100	130-350	180	215	605	100	78	230/400	6200
ZB-ACB-120	190-500	185	230	645	120	113	230/400	6500
ZB-ACB-150	350-800	200	265	700	150	176	230/400	7200
ZB-ACB-180	450-1200	220	305	760	180	254	230/400	8200

Notes: The capacity will be affected by the fluidity, filter fineness and purity of materials.

## The other Products

[Double plate hydraulic screen changer](#)  
[Manual control screen changer](#)  
[Double piston four screen cavities screen changer](#)  
[Automatic mesh belt continuous screen changer](#)  
[Single piston screen changer](#)  
[Single plate screen changer](#)  
[Double piston double screen cavities screen changer](#)  
[Four screen cavities backflash screen changer](#)



Skype: Battemachinery


[info@battemachinery.com](mailto:info@battemachinery.com)  
[sale@meltump.com](mailto:sale@meltump.com)



Skype: Battemachinery

[info@battemachinery.com](mailto:info@battemachinery.com)  
[sale@meltump.com](mailto:sale@meltump.com)

[Single screw gravimetric dosing feeder](#)  
[Single screw gravimetric feeder](#)  
[Twin screw loss in weight metering feeder](#)  
[Twin screw loss in weight feeder](#)  
[Volume feeding machine \(single screw,twin screw\)](#)  
[Micro loss in weight metering feeder](#)  
[Micro loss in weight feeder](#)  
[Liquid loss in weight feeder](#)  
[Multi-component loss in weight feeder](#)



- [ZB-B Gear melt pump](#)
- [ZB-C Extruder melt pump](#)
- [ZB-D Extruding pump for polymer](#)
- [ZB-E Pressurized melt pump](#)
- [ZB-F Melt pump for reaction kettle](#)
- [ZB-H High temperature and high pressure melt pump](#)
- [ZB-K Polymer melt pump](#)
- [ZB-R Gear pump for rubber extruder](#)
- [ZB-U Spinning gear metering pump](#)
- [ZB-X Chemical transporting and dosing pump](#)

Skype: [Battemachinery](#)

[info@battemachinery.com](mailto:info@battemachinery.com)  
[sale@meltump.com](mailto:sale@meltump.com)



<http://www.battemachinery.com/>

Email: [info@battemachinery.com](mailto:info@battemachinery.com)

Skype: [Battemachinery](#)